

FIG. 1





FIG. 2





**FIG. 4**

1000855-102601


111201 5530001


500 →

NODE <u>502</u>	CPU <u>504</u>	RAM <u>506</u>	Swap <u>508</u>	Disk <u>510</u>	Net Card <u>512</u>	O/S Rev <u>514</u>	Patch <u>516</u>	Apps <u>518</u>	Users <u>520</u>	Cluster S/W <u>522</u>
NODE 1	A	A	B	B	A	C	A	B	B	U
NODE 2	A	A	B	B	C	C	A	B	B	B
NODE 3	A	A	A	B	B	A	B	A	A	A
NODE 4	A	A	A	A	B	A	B	B	C	U
NODE 5	A	A	B	B	A	C	A	B	B	B
NODE 6	A	A	B	B	A	C	A	B	B	B


(A) Conforms, (B) Warning, (C) Issue; (U)known

**FIG. 5**






**FIG. 7**



**FIG. 8**



**FIG. 9**




FIG. 10




FIG. 11